

**Heritage Permit Application File #: HP-25-02**  
**13760 Keele Street - Marylake Gatehouse**



**Photo #1:** South facing elevation of gatehouse. Staff note the screened front porch, and windows are not original to the structure.



**Photo #2:** West facing elevation of gatehouse. Staff note the damaged ridge cap along the gable.



**Photo #3:** North facing elevation of gatehouse. Staff note the windows and door are not original to the structure. Staff also note missing slate shingles on the west side of roof.



**Photo #4:** East facing elevation of gatehouse.



**Photo #5:** Photo taken facing northwest. Staff note the screened porch as not being original to the structure.



**Photo #6:** A closer photo of the missing shingles also seen in Photo 3. Staff note the deterioration of remaining shingles.



**Photo #7:** Windows on south facing elevation of gatehouse. Staff note the existing window openings will not be altered, and the proposed windows will be retrofitted into the existing openings.