

Listed Demolition Application
342 Kettleby Road



Photo #1: South facing elevation of subject structure. Staff note the damaged roof, in which a hole is visible beneath the east chimney. Staff also note the rotting/decaying shingles.



Photo #2: East facing elevation of subject structure. Staff note the rotting/decaying state of the window frames and sills.



Photo #3: North facing elevation of subject structure. Staff note extensive deterioration of the rear addition.



Photo #4: West facing elevation of subject structure. Staff note extensive deterioration of the rear addition.



Photo #5: West facing elevation of the subject structure. Staff note the deterioration of the rear addition, including the roof and its elements.



Photo #6: A closer photo of the hole in the roof, also seen in Photo 1. Staff note the deterioration of the remaining shingles and the vegetative growth.



Photo #7: Closer image of east elevation of rear addition. Staff note the significant deterioration and damage to this element of the structure.



Photo #8: Images of the interior provided by the applicant. Staff did not enter the structure due to safety concerns.



Photo #8: Images of the interior provided by the applicant. Staff did not enter the structure due to safety concerns.



Photo #9: Images of the interior provided by the applicant. Staff did not enter the structure due to safety concerns.